HEALTHCARE
Imaging >
Global Support Operations

Field Service Bulletin No. 51

Order No.: DD+DIS065.02E

1 piece UV72O MA1

ADC Compact
Type 5145 / 100/101/140
Type 5145 / 200/201/240

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				X

Please file this document in section 13 of your technical documentation

VME-Cables Repair kit
(CM+9.5145.9350.0)

Problem
During the last months several damaged cables were reported from the field.

Reason
By opening the left door of the digitizer the cables are expanded too much at the hinge. The strands may brake by this high tension.

Solution
A repair kit, containing the most frequently broken cables is available now.

Order number: CM+9.5145.9350.0
Content of the repair kit:
- 1 x cable 2x5p MiniDIN 4.3 m
- 1 x cable 2x9p MiniDIN 4.1 m
- 1 x cable bus VME 2.6 m
- 1 x cable VME/K-erk. 3.7 m
- 1 x cable RMS 4.7 m

Single cables can not be ordered any more because production of ADC Compact stopped in November 2001.

printed in Germany 03 / 2002

AGFA